Civil Engineering Database Subject Heading Index

The **Civil Engineering Database (CEDB)** is designed to provide free, easy bibliographic access to all ASCE publications. The database covers ASCE documents published since 1970. It provides access to all the journals, conference proceedings, books, standards, manuals, magazines, and newspapers. The index terms below were assigned to papers published in this journal during 2003 from a CEDB subject heading list. The CEDB and subject heading list can be accessed on the Web at *http://www.pubs.asce.org/cedbsrch.html*.

Arizona
Method for Forensic Analysis of Residential Floor-Elevation Data. —Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Bedrock
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. —David C. Noe; 17(2), 97-105 (2003).

Bentonite
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. —David C. Noe; 17(2), 97-105 (2003).

Bridge failure
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).

Bridge inspection
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).

Bridge maintenance
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).

Bridges
Fatigue Performance of Modular Bridge Expansion Joints. —Roberto Crocetti and Bo Edlund; 17(4), 167-76 (2003).
Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Bridges, spans
Repair of New Long-Span Bridges Damaged by the 1995 Kobe Earthquake. —John C. Wilson; 17(4), 196-205 (2003).

Building design
Sustainability in Public Facilities: Analysis of Guidance Documents. —Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).
Integrated Development of Facilities Design and Services. — Jan Bröchner; 17(1), 19-23 (2003).
Designing Facilities Management Needs into Infrastructure Projects: Case from a Major Hospital. —Francis T. Edum-Fotwe, C. Egbu, and A. G. F. Gibb; 17(1), 43-50 (2003).

Buildings
Study of Recent Building Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 151-8 (2003).

Buildings, public
Sustainability in Public Facilities: Analysis of Guidance Documents. — Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).

Cement
Condition Assessment of a Deteriorated Cement Works. — W. P. S. Dias and A. D. C. Jayanandana; 17(4), 188-95 (2003).

Cements
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. — Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).

Chemical treatment
Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Collapse
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).
Study of Recent Building Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 151-8 (2003).

Colorado
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. —David C. Noe; 17(2), 97-105 (2003).

Concrete
Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. —P. Reynolds and A. Pavic; 17(2), 75-86 (2003).
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).

Concrete structures
Condition Assessment of a Deteriorated Cement Works. — W. P. S. Dias and A. D. C. Jayanandana; 17(4), 188-95 (2003).

Construction
Sustainability in Public Facilities: Analysis of Guidance Documents. —Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).

Construction materials
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. —Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).

Corrosion
Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Cracking
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. — Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).
Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. — Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

Damage patterns
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. — David C. Noe; 17(2), 97-105 (2003).

Dams, concrete
Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. — Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

Design
Linking Programming and Design with Facilities Management. — Eren Erdener; 17(1), 4-8 (2003).

Documentation
Sustainability in Public Facilities: Analysis of Guidance Documents. —Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).

Durability
Condition Assessment of a Deteriorated Cement Works. — W. P. S. Dias and A. D. C. Jayanandana; 17(4), 188-95 (2003).

Dynamic tests
Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. —P. Reynolds and A. Pavic; 17(2), 75-86 (2003).
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).

Earthquake damage
Repair of New Long-Span Bridges Damaged by the 1995 Kobe Earthquake. —John C. Wilson; 17(4), 196-205 (2003).

Elevation
Method for Forensic Analysis of Residential Floor-Elevation Data. —Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Excitation
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).

Expansion joints
Fatigue Performance of Modular Bridge Expansion Joints. —Roberto Crocetti and Bo Edlund; 17(4), 167-76 (2003).

Facilities
Linking Programming and Design with Facilities Management. — Eren Erdener; 17(1), 4-8 (2003).

Civil Engineering Database Subject Heading Index

The **Civil Engineering Database (CEDB)** is designed to provide free, easy bibliographic access to all ASCE publications. The database covers ASCE documents published since 1970. It provides access to all the journals, conference proceedings, books, standards, manuals, magazines, and newspapers. The index terms below were assigned to papers published in this journal during 2003 from a CEDB subject heading list. The CEDB and subject heading list can be accessed on the Web at *http://www.pubs.asce.org/cedbsrch.html*.

Arizona
Method for Forensic Analysis of Residential Floor-Elevation Data. —Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Bedrock
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. —David C. Noe; 17(2), 97-105 (2003).

Bentonite
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. —David C. Noe; 17(2), 97-105 (2003).

Bridge failure
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).

Bridge inspection
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).

Bridge maintenance
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).

Bridges
Fatigue Performance of Modular Bridge Expansion Joints. —Roberto Crocetti and Bo Edlund; 17(4), 167-76 (2003).
Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Bridges, spans
Repair of New Long-Span Bridges Damaged by the 1995 Kobe Earthquake. —John C. Wilson; 17(4), 196-205 (2003).

Building design
Sustainability in Public Facilities: Analysis of Guidance Documents. —Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).
Integrated Development of Facilities Design and Services. — Jan Bröchner; 17(1), 19-23 (2003).
Designing Facilities Management Needs into Infrastructure Projects: Case from a Major Hospital. —Francis T. Edum-Fotwe, C. Egbu, and A. G. F. Gibb; 17(1), 43-50 (2003).

Buildings
Study of Recent Building Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 151-8 (2003).

Buildings, public
Sustainability in Public Facilities: Analysis of Guidance Documents. — Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).

Cement
Condition Assessment of a Deteriorated Cement Works. — W. P. S. Dias and A. D. C. Jayanandana; 17(4), 188-95 (2003).

Cements
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. — Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).

Chemical treatment
Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Collapse
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).
Study of Recent Building Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 151-8 (2003).

Colorado
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. —David C. Noe; 17(2), 97-105 (2003).

Concrete
Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. —P. Reynolds and A. Pavic; 17(2), 75-86 (2003).
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).

Concrete structures
Condition Assessment of a Deteriorated Cement Works. — W. P. S. Dias and A. D. C. Jayanandana; 17(4), 188-95 (2003).

Construction
Sustainability in Public Facilities: Analysis of Guidance Documents. —Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).

Construction materials
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. —Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).

Corrosion
Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Cracking
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. — Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).
Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. — Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

Damage patterns
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. — David C. Noe; 17(2), 97-105 (2003).

Dams, concrete
Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. — Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

Design
Linking Programming and Design with Facilities Management. — Eren Erdener; 17(1), 4-8 (2003).

Documentation
Sustainability in Public Facilities: Analysis of Guidance Documents. —Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).

Durability
Condition Assessment of a Deteriorated Cement Works. — W. P. S. Dias and A. D. C. Jayanandana; 17(4), 188-95 (2003).

Dynamic tests
Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. —P. Reynolds and A. Pavic; 17(2), 75-86 (2003).
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).

Earthquake damage
Repair of New Long-Span Bridges Damaged by the 1995 Kobe Earthquake. —John C. Wilson; 17(4), 196-205 (2003).

Elevation
Method for Forensic Analysis of Residential Floor-Elevation Data. —Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Excitation
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).

Expansion joints
Fatigue Performance of Modular Bridge Expansion Joints. —Roberto Crocetti and Bo Edlund; 17(4), 167-76 (2003).

Facilities
Linking Programming and Design with Facilities Management. — Eren Erdener; 17(1), 4-8 (2003).

Sustainability in Public Facilities: Analysis of Guidance Documents. — Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).
Adding Value to Constructed Facilities: Facilities Management Hospitality Case Study. — M. I. Okoroh, C. M. Jones, and B. D Ilozor; 17(1), 24-33 (2003).
Integrated Resources Management Structure for Facilities Provision and Management. — Danny Shiem-Shin Then; 17(1), 34-42 (2003).
Designing Facilities Management Needs into Infrastructure Projects: Case from a Major Hospital. — Francis T. Edum-Fotwe, C. Egbu, and A. G. F. Gibb; 17(1), 43-50 (2003).
Framework Model for Asset Maintenance Management. — Mohammad A. Hassanain, Thomas M. Froese, and Dana J. Vanier; 17(1), 51-64 (2003).

Failure investigations
Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. — Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).
Fatigue Performance of Modular Bridge Expansion Joints. —Roberto Crocetti and Bo Edlund; 17(4), 167-76 (2003).

Failures
Study of Recent Building Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 151-8 (2003).

Fatigue
Fatigue Performance of Modular Bridge Expansion Joints. —Roberto Crocetti and Bo Edlund; 17(4), 167-76 (2003).

Finite element method
Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. —P. Reynolds and A. Pavic; 17(2), 75-86 (2003).
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).
Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. —Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

Flexibility
Integrated Development of Facilities Design and Services. — Jan Bröchner; 17(1), 19-23 (2003).

Floors
Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. —P. Reynolds and A. Pavic; 17(2), 75-86 (2003).
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).
Method for Forensic Analysis of Residential Floor-Elevation Data. —Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).
Dynamic Measurements of In-Place Steel Floors to Assess Vibration Performance. —Linda M. Hanagan, Christopher H. Raebel, and Martin W. Trethewey; 17(3), 126-35 (2003).

Forensic engineering
Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. — Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. — David C. Noe; 17(2), 97-105 (2003).
Method for Forensic Analysis of Residential Floor-Elevation Data. — Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Geology
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. — David C. Noe; 17(2), 97-105 (2003).

Grid systems
Adding Value to Constructed Facilities: Facilities Management Hospitality Case Study. — M. I. Okoroh, C. M. Jones, and B. D Ilozor; 17(1), 24-33 (2003).

Heaving
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. — David C. Noe; 17(2), 97-105 (2003).

Highway maintenance
Effectiveness of Preventative Maintenance Treatments Using Fourteen SPS-3 Sites in Texas. —Dar-Hao Chen, Deng-Fong Lin, and Huan-Lin Luo; 17(3), 136-43 (2003).

Hospitals
Designing Facilities Management Needs into Infrastructure Projects: Case from a Major Hospital. —Francis T. Edum-Fotwe, C. Egbu, and A. G. F. Gibb; 17(1), 43-50 (2003).

Information management
Integrated Development of Facilities Design and Services. — Jan Bröchner; 17(1), 19-23 (2003).

Japan
Repair of New Long-Span Bridges Damaged by the 1995 Kobe Earthquake. —John C. Wilson; 17(4), 196-205 (2003).

Leveling
Method for Forensic Analysis of Residential Floor-Elevation Data. —Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Maintenance
Framework Model for Asset Maintenance Management. — Mohammad A. Hassanain, Thomas M. Froese, and Dana J. Vanier; 17(1), 51-64 (2003).

Management
Linking Programming and Design with Facilities Management. — Eren Erdener; 17(1), 4-8 (2003).
Sustainability in Public Facilities: Analysis of Guidance Documents. —Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).
Adding Value to Constructed Facilities: Facilities Management Hospitality Case Study. —M. I. Okoroh, C. M. Jones, and B. D Ilozor; 17(1), 24-33 (2003).
Integrated Resources Management Structure for Facilities Provision and Management. —Danny Shiem-Shin Then; 17(1), 34-42 (2003).
Designing Facilities Management Needs into Infrastructure Projects: Case from a Major Hospital. —Francis T. Edum-Fotwe, C. Egbu, and A. G. F. Gibb; 17(1), 43-50 (2003).

Manufacturing facilities
Integrated Development of Facilities Design and Services. — Jan Bröchner; 17(1), 19-23 (2003).

Measurement
Dynamic Measurements of In-Place Steel Floors to Assess Vibration Performance. — Linda M. Hanagan, Christopher H. Raebel, and Martin W. Trethewey; 17(3), 126-35 (2003).

Modal analysis
Dynamic Measurements of In-Place Steel Floors to Assess Vibration Performance. — Linda M. Hanagan, Christopher H. Raebel, and Martin W. Trethewey; 17(3), 126-35 (2003).

Models
Integrated Resources Management Structure for Facilities Provision and Management. — Danny Shiem-Shin Then; 17(1), 34-42 (2003).
Framework Model for Asset Maintenance Management. — Mohammad A. Hassanain, Thomas M. Froese, and Dana J. Vanier; 17(1), 51-64 (2003).

Nondestructive tests
Condition Assessment of a Deteriorated Cement Works. — W. P. S. Dias and A. D. C. Jayanandana; 17(4), 188-95 (2003).

Pavements
Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. —Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).
Effectiveness of Preventative Maintenance Treatments Using Fourteen SPS-3 Sites in Texas. —Dar-Hao Chen, Deng-Fong Lin, and Huan-Lin Luo; 17(3), 136-43 (2003).

Pools
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. —Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).

Rehabilitation
Repair of New Long-Span Bridges Damaged by the 1995 Kobe Earthquake. —John C. Wilson; 17(4), 196-205 (2003).
Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Residential location
Method for Forensic Analysis of Residential Floor-Elevation Data. —Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Schools
Sustainability in Public Facilities: Analysis of Guidance Documents. —Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).

Sealing
Effectiveness of Preventative Maintenance Treatments Using Fourteen SPS-3 Sites in Texas. —Dar-Hao Chen, Deng-Fong Lin, and Huan-Lin Luo; 17(3), 136-43 (2003).

Serviceability
Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. —P. Reynolds and A. Pavic; 17(2), 75-86 (2003).
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).
Dynamic Measurements of In-Place Steel Floors to

Assess Vibration Performance. — Linda M. Hanagan, Christopher H. Raebel, and Martin W. Trethewey; 17(3), 126-35 (2003).

Statistical analysis

Method for Forensic Analysis of Residential Floor-Elevation Data. — Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Steel

Dynamic Measurements of In-Place Steel Floors to Assess Vibration Performance. — Linda M. Hanagan, Christopher H. Raebel, and Martin W. Trethewey; 17(3), 126-35 (2003).

Stiffness

Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. — Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).

Structural settlement

Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. — David C. Noe; 17(2), 97-105 (2003).

Temperature effects

Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. — Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

Texas

Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. — Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).

Effectiveness of Preventative Maintenance Treatments Using Fourteen SPS-3 Sites in Texas. — Dar-Hao Chen, Deng-Fong Lin, and Huan-Lin Luo; 17(3), 136-43 (2003).

Thermal stresses

Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. — Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

United States

Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).

Study of Recent Building Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 151-8 (2003).

Vibration

Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. — P. Reynolds and A. Pavic; 17(2), 75-86 (2003).

Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).

Dynamic Measurements of In-Place Steel Floors to Assess Vibration Performance. — Linda M. Hanagan, Christopher H. Raebel, and Martin W. Trethewey; 17(3), 126-35 (2003).

West Virginia

Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Author Index

Beasley, Kimball J.
Failure of Exposed Concrete Caused by Corrosion of Embedded Steel. —Kimball J. Beasley; 17(3), 107-8 (2003).

Bilyeu, John
Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. —Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).

Bosch, Sheila J.
Sustainability in Public Facilities: Analysis of Guidance Documents. —Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).

Bröchner, Jan
Integrated Development of Facilities Design and Services. — Jan Bröchner; 17(1), 19-23 (2003).

Carper, Kenneth L.
Editor's Note. —Kenneth L. Carper; 17(1), 1 (2003).
Editor's Note. —Kenneth L. Carper; 17(2), 65 (2003).
Editor's Note. —Kenneth L. Carper; 17(3), 109 (2003).
Editor's Note. —Kenneth L. Carper; 17(4), 159-62 (2003).

Chamarthy, Ram
Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Chen, Dar-Hao
Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. —Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).
Effectiveness of Preventative Maintenance Treatments Using Fourteen SPS-3 Sites in Texas. —Dar-Hao Chen, Deng-Fong Lin, and Huan-Lin Luo; 17(3), 136-43 (2003).

Cho, Eung Ha
Corrosion Condition Evaluation at Muddy Creek Bridge. — Eung Ha Cho and Ram Chamarthy; 17(4), 206-9 (2003).

Crocetti, Roberto
Fatigue Performance of Modular Bridge Expansion Joints. —Roberto Crocetti and Bo Edlund; 17(4), 167-76 (2003).

Dias, W. P. S.
Condition Assessment of a Deteriorated Cement Works. — W. P. S. Dias and A. D. C. Jayanandana; 17(4), 188-95 (2003).

Edlund, Bo
Fatigue Performance of Modular Bridge Expansion Joints. —Roberto Crocetti and Bo Edlund; 17(4), 167-76 (2003).

Edum-Fotwe, Francis T.
Designing Facilities Management Needs into Infrastructure Projects: Case from a Major Hospital. — Francis T. Edum-Fotwe, C. Egbu, and A. G. F. Gibb; 17(1), 43-50 (2003).

Egbu, C.
Designing Facilities Management Needs into Infrastructure Projects: Case from a Major Hospital. — Francis T. Edum-Fotwe, C. Egbu, and A. G. F. Gibb; 17(1), 43-50 (2003).

Erdener, Eren
Linking Programming and Design with Facilities Management. — Eren Erdener; 17(1), 4-8 (2003).

Froese, Thomas M.
Framework Model for Asset Maintenance Management. — Mohammad A. Hassanain, Thomas M. Froese, and Dana J. Vanier; 17(1), 51-64 (2003).

Gibb, A. G. F.
Designing Facilities Management Needs into Infrastructure Projects: Case from a Major Hospital. — Francis T. Edum-Fotwe, C. Egbu, and A. G. F. Gibb; 17(1), 43-50 (2003).

Hadipriono, Fabian C.
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).
Study of Recent Building Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 151-8 (2003).

Hanagan, Linda M.
Dynamic Measurements of In-Place Steel Floors to Assess Vibration Performance. —Linda M. Hanagan, Christopher H. Raebel, and Martin W. Trethewey; 17(3), 126-35 (2003).

Hassanain, Mohammad A.
Framework Model for Asset Maintenance Management. — Mohammad A. Hassanain, Thomas M. Froese, and Dana J. Vanier; 17(1), 51-64 (2003).

Hudyma, Nick
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. —Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).

Husein Malkawi, Abdallah I.
Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. —Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

Ilozor, B. D
Adding Value to Constructed Facilities: Facilities Management Hospitality Case Study. —M. I. Okoroh, C. M. Jones, and B. D Ilozor; 17(1), 24-33 (2003).

Ilozor, Benedict Dozie
Exploring Facilities Management. — Benedict Dozie Ilozor; 17(1), 2-3 (2003).

Jayanandana, A. D. C.
Condition Assessment of a Deteriorated Cement Works. — W. P. S. Dias and A. D. C. Jayanandana; 17(4), 188-95 (2003).

Jones, C. M.
Adding Value to Constructed Facilities: Facilities Management Hospitality Case Study. — M. I. Okoroh, C. M. Jones, and B. D Ilozor; 17(1), 24-33 (2003).

Karakouzian, Moses
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. — Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).

Lin, Deng-Fong
Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. — Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).
Effectiveness of Preventative Maintenance Treatments Using Fourteen SPS-3 Sites in Texas. —Dar-Hao Chen, Deng-Fong Lin, and Huan-Lin Luo; 17(3), 136-43 (2003).

Luo, Huan-Lin
Effectiveness of Preventative Maintenance Treatments Using Fourteen SPS-3 Sites in Texas. —Dar-Hao Chen, Deng-Fong Lin, and Huan-Lin Luo; 17(3), 136-43 (2003).

Mailvaganam, Noel P.
Axioms For Building and Repairing Durable Concrete Structures. —Noel P. Mailvaganam and A. Wiseman; 17(4), 163-6 (2003).

McCue, James D.
Structural Defect Discovered During Roof Replacement. — James D. McCue and David H. Nicastro; 17(2), 66 (2003).

Miguel, George P.
Method for Forensic Analysis of Residential Floor-Elevation Data. —Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Mutasher, Saad A.
Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. —Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

Nicastro, David H.
Structural Defect Discovered During Roof Replacement. — James D. McCue and David H. Nicastro; 17(2), 66 (2003).

Noe, David C.
Case History of Damage to a School Building Caused by Differentially Heaving Bedrock. —David C. Noe; 17(2), 97-105 (2003).

Okoroh, M. I.
Adding Value to Constructed Facilities: Facilities Management Hospitality Case Study. — M. I. Okoroh, C. M. Jones, and B. D Ilozor; 17(1), 24-33 (2003).

Okuyan, Mehmet N.
Alkali-Silica Reaction—Possible Cause of Map Cracking in Gunite. — Moses Karakouzian, Mehmet N. Okuyan, and Nick Hudyma; 17(3), 118-25 (2003).

Pavic, A.
Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. — P. Reynolds and A. Pavic; 17(2), 75-86 (2003).
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).

Pearce, Annie R.
Sustainability in Public Facilities: Analysis of Guidance Documents. — Sheila J. Bosch and Annie R. Pearce; 17(1), 9-18 (2003).

Qiu, Tony J.
Thermal-Structural Modeling and Temperature Control of Roller Compacted Concrete Gravity Dam. — Abdallah I. Husein Malkawi, Saad A. Mutasher, and Tony J. Qiu; 17(4), 177-87 (2003).

Raebel, Christopher H.
Dynamic Measurements of In-Place Steel Floors to Assess Vibration Performance. — Linda M. Hanagan, Christopher H. Raebel, and Martin W. Trethewey; 17(3), 126-35 (2003).

Reynolds, P.
Effects of False Floors on Vibration Serviceability of Building Floors. I: Modal Properties. — P. Reynolds and A. Pavic; 17(2), 75-86 (2003).
Effects of False Floors on Vibration Serviceability of Building Floors. II: Response to Pedestrian Excitation. — P. Reynolds and A. Pavic; 17(2), 87-96 (2003).

Scullion, Tom
Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. — Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).

Then, Danny Shiem-Shin
Integrated Resources Management Structure for Facilities Provision and Management. — Danny Shiem-Shin Then; 17(1), 34-42 (2003).

Trethewey, Martin W.
Dynamic Measurements of In-Place Steel Floors to Assess Vibration Performance. — Linda M. Hanagan, Christopher H. Raebel, and Martin W. Trethewey; 17(3), 126-35 (2003).

Vanier, Dana J.
Framework Model for Asset Maintenance Management. — Mohammad A. Hassanain, Thomas M. Froese, and Dana J. Vanier; 17(1), 51-64 (2003).

Walsh, Kenneth D.
Method for Forensic Analysis of Residential Floor-Elevation Data. — Kenneth D. Walsh and George P. Miguel; 17(3), 110-7 (2003).

Wardhana, Kumalasari
Analysis of Recent Bridge Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 144-50 (2003).
Study of Recent Building Failures in the United States. — Kumalasari Wardhana and Fabian C. Hadipriono; 17(3), 151-8 (2003).

Wilson, John C.
Repair of New Long-Span Bridges Damaged by the 1995 Kobe Earthquake. — John C. Wilson; 17(4), 196-205 (2003).

Wiseman, A.
Axioms For Building and Repairing Durable Concrete Structures. — Noel P. Mailvaganam and A. Wiseman; 17(4), 163-6 (2003).

Zhou, Fujie
Forensic Evaluation of Premature Failures of Texas Specific Pavement Study–1 Sections. — Dar-Hao Chen, John Bilyeu, Tom Scullion, Deng-Fong Lin, and Fujie Zhou; 17(2), 67-74 (2003).